

Alyeska Pipeline Service Company Pump Station Investigation Boring Log

Boring No. 8 - 15 Type Of Boring 36" DIA. DRILLING BUCKET
 Grid Location N 10+05 E 7+95 Casing Size & Depth NONE
 Surface Elevation 1010 Remarks _____
 Date Drilled 12/21/70

Depth Feet	Frozen or Nonfrozen	SAMPLE					Soil Graph	DESCRIPTION	Moisture Content, %	Dry Density pcf	Other Tests
		Type	Number	Location	Recovery	Blows/Ft.					
0							ORGANICS				
0-1							WET BROWN, SANDY CLAY WITH 30 TO 40% WEATHERED SCHIST FRAGMENTS				
1-2							(FILL?)				
2-20		B	1				TAN TO BROWN GRAY, HIGHLY WEATHERED SCHIST WITH NUMEROUS BROWN TO GRAY, WET CLAY SEAMS. SURROUNDING ROCK FRAGMENTS APPEAR SLICKENSIDED. ← SMALL SEEP				
20-22							TAN MOTTLED GRAY, DAMP, HIGHLY TO MODERATELY WEATHERED SCHIST				

Job No. S-12140-TAPS/152

WOODWARD-LUNDGREN & ASSOCIATES

Figure 7