

Alyeska Pipeline Service Company Pump Station Investigation Boring Log

Boring No. 8 - 15 (CONTINUED)

Depth Feet	Frozen or Nonfrozen	SAMPLE					Soil Graph	DESCRIPTION	Moisture Content, %	Dry Density pcf	Other Tests
		Type	Number	Location	Recovery	Blows / Ft.					
25							TAN MOTTLED GRAY, DAMP, HIGHLY TO MODERATELY WEATHERED SCHIST				
30							GRAY, DAMP, MODERATELY WEATHERED SLICKENSIDED SCHIST				
35							BOTTOM OF BORING AT 31.0', DRY AT TIME OF DRILLING				