Alyeska Pipeline Service Company Pump Station Investigation Boring Log

Boring No. 8 - 21 (CONTINUED)

Depth Feet	Frozen or Nonfrozen	SAMPLE Type	Number	Location	Recovery	Blows/Ft.	Soil Graph	DESCRIPTION	Moisture Content, %	Dry Density pcf	Other Tests
25								TAN ORANGE, MOIST, HIGHLY WEATHERED SCHIST			
30								BOTTOM OF BORING AT 28.5', DRY AT TIME OF DRILLING			

Job No. S-12140-TAPS/152 | WOODWARD-LUNDGREN & ASSOCIATES | Figure 17